



### JOB HAZARD ANALYSIS & WORK METHOD STATEMENT WORKSHEET

Job No: <u>12345</u>		Date: <u>9 August 2006</u>		Rev No: <u>1</u>		Prepared By: <u>Joe Permit Holder</u>		Approved By: <u>Joe Permit Issuer</u>	
Job Description: <u>Paint the underside of the canopy using a scissorlift</u>									
<b>JHA Team to print name and sign to signify that you have read, understood and accept the control measures defined in this JHA:</b>									
Name <u>Joe Permit Holder</u>			Name <u>Joe Apprentice</u>			Name _____			
Signature _____			Signature _____			Signature _____			
<b>Type of Work Permit Required (Please indicate by marking "Y" or "N"):</b>									
Hot Work in hazardous area [ ]		Flaring of flammable gas [ ]		Other (list below) [ X ]		<i>For further information on Work Procedures or PPE refer to:</i> 1. Relevant Material Safety Data Sheets 2. Statutory requirements 3. Relevant Codes of Practice 4. Relevant Attachments to Permit			
Confined Space Entry [ ]		Live electrical line work [ ]		<u>Working at Height above 2 meters</u>					
Excavation > / = 1.5 m [ ]		Explosive Blasting [ ]		_____					
<b>PPE Requirements</b>									
Safety Glasses [ x ]		Dust Masks [ x ]		Barricading/Signs [ x ]		High visibility vest [ x ]			
Faceshield [ ]		Safety Harness [ ]		Safety Boots [ ]		Other (list below) [ ]			
Respirator [ ]		Gloves [ x ]		Fire Extinguisher [ x ]		_____			
<i>Minimum requirements for all personnel shall be: High visibility vest and safety boots.</i>									
Job Specific Equipment: <u>Workers will access the underside of the canopy via a scissorlift with proper guard rail, mid rail and toe board.</u>									
<u>A roller will be used to paint. Safety glasses, dust masks, high visibility vest, safety boots and gloves must be worn at all times.</u>									
<u>The dispenser island area will be completely barricaded with cones, flags and caution tape. No access by vehicles or pedestrians will be allowed.</u>									