

Procedure Name	Reference Paragraph	Description	Interval	Responsibility
System Startup	3.1	How to start the Ultrapointe application program	N/A	Customer
System Shutdown	3.2	Shutdown procedure for the LIS in preparation for power off	N/A	Customer
Lockup Recovery	3.3	Procedures for recovery from software lockups	N/A	Customer
Wafer Removal	3.4	Wafer removal procedures in the event of a lockup or failure	N/A	Customer
Wipe Down	3.5	Wipe down of the exterior of the machine	Daily	Customer
Backup Data	3.6	Procedure to backup critical data to tape	Weekly	Customer
Chuck Cleaning	3.7	Cleaning procedures for the chuck and robot end effector	Weekly	Customer
Laser Life and Interlock Check	3.8	Test procedure for the laser system to determine whether to schedule laser service, and to verify interlock integrity	Monthly	Customer