



Fig. 12-20. Auxiliary-View Problems. Using Layout C (Appendix, page 474), make complete mechanical drawing of problem assigned. Omit pictorial drawings, spacing dimensions, and instructional notes. Include complete dimensions, moving dimensions from pictorials to the views.