

————— 0—0.000

$\frac{1}{64}$.015625
 $\frac{1}{32}$.03125
 $\frac{3}{64}$.046875
 $\frac{1}{16}$.0625
 $\frac{5}{64}$.078125
 $\frac{3}{32}$.09375
 $\frac{7}{64}$.109375
 $\frac{1}{8}$.125
 $\frac{9}{64}$.140625
 $\frac{5}{32}$.15625
 $\frac{11}{64}$.171875
 $\frac{3}{16}$.1875
 $\frac{13}{64}$.203125
 $\frac{7}{32}$.21875
 $\frac{15}{64}$.234375
 $\frac{1}{4}$.250

$\frac{17}{64}$.265625
 $\frac{9}{32}$.28125
 $\frac{19}{64}$.296875
 $\frac{5}{16}$.3125
 $\frac{21}{64}$.328125
 $\frac{11}{32}$.34375
 $\frac{23}{64}$.359375
 $\frac{3}{8}$.375
 $\frac{25}{64}$.390625
 $\frac{13}{32}$.40625
 $\frac{27}{64}$.421875
 $\frac{7}{16}$.4375
 $\frac{29}{64}$.453125
 $\frac{15}{32}$.46875
 $\frac{31}{64}$.484375
 $\frac{1}{2}$.500

$\frac{33}{64}$.515625
 $\frac{17}{32}$.53125
 $\frac{35}{64}$.546875
 $\frac{9}{16}$.5625
 $\frac{37}{64}$.578125
 $\frac{19}{32}$.59375
 $\frac{39}{64}$.609375
 $\frac{5}{8}$.625
 $\frac{41}{64}$.640625
 $\frac{21}{32}$.65625
 $\frac{43}{64}$.671875
 $\frac{11}{16}$.6875
 $\frac{45}{64}$.703125
 $\frac{23}{32}$.71875
 $\frac{47}{64}$.734375
 $\frac{3}{4}$.750

$\frac{49}{64}$.765625
 $\frac{25}{32}$.78125
 $\frac{51}{64}$.796875
 $\frac{13}{16}$.8125
 $\frac{53}{64}$.828125
 $\frac{27}{32}$.84375
 $\frac{55}{64}$.859375
 $\frac{7}{8}$.875
 $\frac{57}{64}$.890625
 $\frac{29}{32}$.90625
 $\frac{59}{64}$.921875
 $\frac{15}{16}$.9375
 $\frac{61}{64}$.953125
 $\frac{31}{32}$.96875
 $\frac{63}{64}$.984375
————— 1—1.000