

Premix drums of struvite slurry



Load drums of slurry into conversion vessel



Run conversion process



Pump out of conversion vessel into hot surge tank



Pump dittmarite solution to paper making process